

Under Review Notification

Raised By: Steven Drouin

Product #: D119-827

Date: 19.06.19

Product Name: Tail Rotor Pedal Lockout

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank								Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
D119-827-011	IIN-D119-827 Rev. E	Y	Y	N	N	N	N	Y	Y	19-914	CHG#002
D119-827-013	IIN-D119-827 Rev. E	Y	Y	N	N	N	N	Y	Y	19-914	CHG#001
D4703-041	D4703 Rev B	Y	Y	N	N	N	N	Y	Y	19-914	Drawing update
D4703-045	D4703 Rev B	Y	Y	N	N	N	N	Y	Y	19-914	Drawing update

Description of Issue:

Need to perform a verification on the following product D4703-041 and D4703-045 also with the kits that involved those parts.

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

QC Coordinator

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider

Supply Chain Director / Senior Buyer

Marketing Eugene